ECS Configuration Change Request							age i or		Page(		
1. Originator Eric T. Obligacion	2. Log Date 9809	e:	3. CCR#:		4. Re	1	<b>5</b> . Tel: 301-614-51		S. Off:	7. Org.	
8. Title of Change: Relocation			rom W25 to W	V30A				1	7	(43	
J. Origingson Organization		10. Date:	0/98	11. Class		12. Type: CCR		13. Need Date: 08/28/98 9/18/98			
14. Office Manager Signature		15.	Date:	16. Date CCB Decision Nee		ad.	17. Cat Change	<b>-</b> -		. Priority: gent	
Mary Koth		18/	120/98	08/25/98 9/			THE C	other			
19. Documentation/Drawing				ule Impact:			21. CI(s) Affected:DIPHW a		V and		
Cable Configuration Management Plan 920-106-005 1814 None											
GDAAC Physical Floor Plan 930 - 7DG - COU REV 6											
22. Release Affected:			23. Date due		Impl.	Date:		Effectivity		26. Est. Cost None	
Release B						<del>28/98</del> 9/13/98		Change: Co		Cost None	
· · · · · · · · · · · · · · · · · · ·			7						Other:		
27. Source Reference: UNCR (attach) MACGONITIEM GOLDON GOLDON											
28. Description of Change	e: (use additio	nal Sheets	if necessary	() 		.ith th	CDAAC 4	ietrihution n	nailroom	This	
The DIPHW and ICLHW systems currently located in W25 is sharing the same room with the GDAAC distribution mailroom. This mailroom is currently in process of expanding storage area. This will affect the current floor space that the systems are using.											
mailroom is currently in process of expanding storage area. This will allook the current hoor space with the system of the syste											
10-14	no additional	shoots if no	ecessary)								
29. Proposed Solution: (use additional sheets if necessary) Relocate both ICLHW and DIPHW to W30A.											
Relocate both tochtv and b	11 1111 10 1100.	•									
										•	
30. Alternate Solution: (use additional sheets if necessary)											
None, GDAAC mail distribution needs the floor space for additional storage racks.											
-											
31. Consequences if Char	nge(s) are not	approved:	(use additio	nal sheets	if nec	essary	()	: Tomn	aratura s	and air	
		auad ta tha	CIDA AT THA IA	nm wiinnui	anne	- 5046	* 10 DE OIL	me. rempo	rocess.	and an	
The DIPHW and ICLHW will be stacked moved to the side of the footh, without display open of the mail process. circulation environment would be a factor for equipment damage because of the materials to be stored by the mail process.											
		_									
32. Does Change Affect Any of the following (Please Explain on additional sheet):  ☐ Maintenance Training ☐ Performance ☐ Operation Training ☐ Safety ☐ Service ☐ Support ☐ Test ☐ Maintenance ☐ Operation Training ☐ Operation ☐ Operati											
33 Organization(s) Affected: XCM											
Jo. Olamination(o)	∏QO	<b>L</b> ⊠ Rel	Dev [	Procureme	ent	RTS	_	JSci. Data E	ing ∐	Security	
		ev. Sys		Sys Verf A		Oth		SMC	ΠΔK I		
34. Site(s) Affected:	EDF	DAAC []\	/ATC □ED	C ⊠GSFC		arc	Пиэрс				
35. Board Comments:								36. Worl			
,								Eric	- 6/1	gazion	
37. Release Authorized (For CM Use Only):   Yes   No   38. CM Verified/Signature and Date											
39. EDF/REL2 OCB Chair	nSign/Date):	40	). Dispositio	n: MApp	□A	p/C	41. E	SDIS ERB	Concur	rence:	
JS. EUF/RELZ CO GIAN			□DisApr	proved [	]Withd						
7W Fish	9/17/	58	□Fwd/E		d/ESE						
42. ECS CCB Chair (Sign			Disposition		A/C	_	44. C	CR Closed	Date:		
		j	DisApprove	ed[_] With	hdraw		l				

CM01AU98